

消防處
牌照及審批總區
通風系統課

九龍啓德道五號
啓德政府大樓四樓四一六室



FIRE SERVICES DEPARTMENT
LICENSING & CERTIFICATION COMMAND
Ventilation Division

Room 416, 4/F., Kai Tak Government Building,
No. 5 Arrivals Road, Kowloon.

本處編號 Our Ref.: FP 315/13
來函編號 Your Ref.: L889
圖文傳真 Fax: 852-2382 2495
電話 Tel. No.: 852-2251 4140

18 October 2001

Messrs. JENXON Ltd.,
Rm.701 - 704,
No. 341 King's Road,
North Point
Hong Kong.

(Attn. Mr. Paul CHAN)

Dear Sir,

**"ACTIONAIR." Hot/Shield Combination smoke Management
and Fire Damper Operated By Hytork Pneumatic Actuator**

After scrutiny of the test/assessment reports attached to your letter dated 16.08.2001, I wish to inform you that I have no objection in principle to the use of "ACTIONAIR" hot/shield combination smoke management and fire damper operated by "Hytork" pneumatic actuator in smoke extraction system based on the following details:

| | |
|-------------------------------------|----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| Manufacturer | : Ruskin Air Management Ltd. (Formerly known as Baxi air Management Ltd.) |
| Product | : "Actionair" Hot/Shield Series 2501, 2601 and 2701 Combination Smoke Management and Fire Damper operated by "Hytork" (EDN0070 Q-17 pneumatic return string actuator (Assessed by LPC to BS 476 Part 20: 1987 Project No. 87311) |
| Maximum Damper Size | : Rectangle: 1000mm x 1000mm Circular: 1000mm dia. Oval: 1000mm x 500mm |
| Temperature Exposure & Test Reports | : By Colt International Limited and were witnessed by Loss Prevention Council and BRE: PR-98-21-10 dated 21 October 1998 |

- 2 -

Assessment Report : BRE assessment report number CC 91915 dated 24 July 2001.

Result : Satisfy the requirement of temperature exposure test with cyclic operation test at 250°C for one hour

Remarks

This assessment is subject to review by July 2006.

Yours faithfully,



(TSE Kiu-cheung)
for Director of Fire Services